

# CAUTION

## “KNEE MILL” MILLING MACHINE

### WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of all dangerous moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing.
- Securely clamp workpiece to table.
- Do not reach over moving machinery to activate controls.
- Use spring-loaded operating handles when work table is power fed.
- Cover and store all unused cutters.
- Use barrier guards when conducting “fly cutting” operations.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

Immediately report all machinery malfunctions