

CAUTION

BUFFING POLISHING MACHINE

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Do not mix incompatible dusts (ex: steel and aluminum).
- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing.
- Dust collection system, if provided, is connected and operational.
- Do not wear gloves, jewelry, or loose clothing.
- Do not reach over moving machinery to activate controls.
- Use proper type of polishing wheel for material being processed.
- Polish only on side of wheels designed for side polishing.
- De-energize and lockout machine before making adjustments/ repairs.
- Ensure that operator is properly trained and has read owners operation manual.

Immediately report all machinery malfunctions