

CAUTION

CHOP SAW

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing.
- Dust collection system, if provided, is connected and operational.
- Use proper blade to cut material.
- Replace dull, cracked, or excessively fouled saw blades.
- Securely clamp workpiece prior to cutting.
- Never clamp or wedge guard in open position.
- Replace/repair spring-loaded trigger switches that “stick”.
- Do not wear gloves, jewelry, or loose clothing.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Ensure that operator is properly trained and has read owners operation manual.

Immediately report all machinery malfunctions