

CAUTION

DROP HAMMER

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Keep work area clean. Foreign materials may cause poor footing.
- Do not operate machine if unauthorized persons are present.
- All overhead machinery parts secured to prevent falling components.
- Use hand tools for all piecework feeding.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

Immediately report all machinery malfunctions