

# CAUTION

## METAL CUTTING (HORIZONTAL) BAND SAW

### WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of all dangerous moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing.
- Inspect blades for broken or dull saw teeth, excessive gumming, and fouling.
- Adjust blade guards to cover unused portion of blade.
- Adjust blade tension properly.
- Use saw blade designed for material being cut.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

---

Immediately report all machinery malfunctions