

# CAUTION

## **RADIAL ARM SAW** **WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT**

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
  - Beware of all dangerous moving machinery parts.
  - Keep work area clean. Foreign materials may cause poor footing
  - Dust collection system, if provided, is connected and operational.
  - Saw must gently return to starting position when released.
  - Use stick or brush to remove small scrap from work table.
  - Use proper saw blade for material being cut.
  - Replace dull, cracked, or excessively fouled saw blades.
  - Do not use abrasive, cutoff, or wire wheels on radial arm saws.
  - Saw blade must never travel beyond working edge of table; forward travel stop is properly adjusted.
  - When cross-cutting, use workpiece clamps to prevent “kickback” hazards.
  - When ripping, kickback dogs must be used and properly adjusted.
  - Never exceed rated RPM of saw blade.
  - Follow manufacturer requirements for cutting ferrous and nonferrous metals.
  - De-energize and lockout all energy systems before making adjustments/ repairs.
  - Do not wear gloves, jewelry, or loose clothing.
  - Ensure that operator is properly trained and has read owners operation manual.
- Immediately report all machinery malfunctions**
-