

# CAUTION

## WOOD WORKING LATHE

### WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of all dangerous moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing.
- Store unused chisels and gouges in tool racks.
- Do not use chisels and gouges with missing or broken handles.
- Be sure of operating speed before beginning work.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

Immediately report all machinery malfunctions